

IOWA WEATHERIZATION PROGRAM NOTICE 23-02

TO: Weatherization Coordinators  
FROM: Christine Taylor, Weatherization Program Manager  
DATE: September 5, 2023  
RE: Door and Window Replacement  
Effective: September 6, 2023

As of September 6, 2023, door and window replacements must be charged as an Energy Conservation Measure (ECM) or as a Health & Safety Measure (HSM). Door and window replacements cannot be charged as an Incidental Repair Measure (IRM) because it is not included in our State Plan.

Replacement as an ECM = charge to regular DOE, DOE-BIL, or HEAP  
Replacement as an HSM = charge to HEAP

When entering the door or window to be replaced in the NEAT/MHEA Audit, do not activate the “include in SIR” box.

Pictures showing the need for a replacement as well as pictures of the new doors and windows is required.